

TSM11 Daisy Chain Connector Board Assembly Guide Requirements

- TSM11x-xRM integrated Step-Servo Motor
- Daisy Chain Connection board (PN: 8500-005)
- 2 Assembly Screws (Included)
- Compatible Motor Labels (Included)
- Compatible philips screwdriver (#0 recommended)

Before you start, please make sure your TSM11 motor is powered off and 12 Pin connector is not connected to the motor

Step 1

- Peel off the Motor part number label on the side of the motor
- Locate two Screw holes on the side of your TSM11 motor




- Stick the Part number label on the "Warning label" side of the motor




Note: Please KEEP the Part Number Label on the Motor for product Warranty.

Step2

- Connect the 12 Pin connector from the daisy chain board to the TSM11 Motor connector





- Align the two assembly holes with the Screw holes on the TSM11 Motor
- Mount the board with the screws provided and secure them tight



Step3

- Put the connector guide label on the top of the daisy chain communication board



- For more details on how to use your TSM11 integrated Step-Servo Motor, please refer to TSM11 Quick Set Guide or Hardware manual.

If you have any questions or comments, please call Applied Motion Products Customer Support: (800) 525-1609, or visit us online at www.applied-motion.com.



404 Westridge Dr.
Watsonville, CA 95076, USA
1-800-525-1609
Tel (831) 761-6555
www.applied-motion.com